

PO Facility Risk Assessment

Name(s) of Risk Team Members: R. Gill, K. Klaus, K. Kusche, R. Liegel, S. Shapiro, M. Zarcone	Point Value → Parameter ↓	1	2	3	4	5
Area/Facility Description Title: General Housekeeping	Occupancy or Use	≤once/year	≤once/month	≤once/week	≤once/shift	>once/shift
Area/Facility # (if applicable): PO-FRA-002						
Area/Facility Description: Physics Department Spaces	Severity	First Aid Only	Medical Treatment	Lost Time	Partial Disability	Death or Permanent Disability
Date: May 19, 2005 Rev.#: 0	Likelihood	Extremely Unlikely	Unlikely	Possible	Probable	Multiple
Reason for Revision (if applicable):				Comments:		

Physical Item or Activity	Hazard(s)	Control(s)	Risk with Controls in Place				Control(s) Added to Reduce Risk	Risk with Additional Controls in Place				% Risk Reduction
			Occupancy A	Severity B	Likelihood C	Risk* AxBxC		Occupancy A	Severity B	Likelihood C	Risk* AxBxC	
Walking & working surfaces	Falls on same level	Tier 1; work planning; P.E. scheduled maintenance; internal and external audits; posting; labeling; training; barriers; communication; lessons learned	5	3	4	60	Mats placed inside all entrances to keep floors dry; ice melt chemicals available for spreading	5	3	3	45	25
Storage	Being struck by object	Tier 1; work planning; P.E. scheduled maintenance; internal and external audits; posting; labeling; training; barriers; communication; lessons learned	5	2	3	30						
Paper storage in offices	Fire loading	Tier 1; internal and external audits; communication; life safety codes	5	2	2	20						
Egress	Blocked egress	Tier 1; work planning; training; barriers; communication; lessons learned; life safety codes; emergency preparedness; aisles are unobstructed; aisles and stairwells adequately illuminated	5	2	2	20						

PO Facility Risk Assessment

			Risk with Controls in Place					Risk with Additional Controls in Place				
Physical Item or Activity	Hazard(s)	Control(s)	Occupancy A	Severity B	Likelihood C	Risk* AxBxC	Control(s) Added to Reduce Risk	Occupancy A	Severity B	Likelihood C	Risk* AxBxC	% Risk Reduction
Air quality	Allergies and respiratory problems	Tier 1; P.E. scheduled maintenance; internal and external audits; report problems to building manager	5	2	3	30						
Further Description of Controls Added to Reduce Risk:												
*Risk:	0 to 20 Negligible	21 to 40 Acceptable	41 to 60 Moderate				61 to 80 Substantial			81 or greater Intolerable		